

1. Prepare the following tools: glue, pencil, brush, heat gun or hair drier and blunt scraper (avoid too sharp to damage the board)



2. Find a right place and draw a circle



3. Glue evenly on the bottom of D-ring patch and board.



4. Dry the glued area for 3-5 minutes, just not sticky is ok.



5. Heat the glued area evenly with the hot gun/hair drier, as the glue will work better after heating.



6. Stick the D-ring patch to the board.





7. Press the patch flat with the scraper. Finish!

